

Middleton Tyas

10/12/17

Deers Sir,

I wish to bring the following to the Committee's attention which concern me and possibly other residents as follows

Junction at the corner of School Bank and the Strand on the road to/from Moulton is unsafe and dangerous. I have had 2 near misses recently either by having to use the middle of the road in both directions to see what is coming or take a chance that the road was clear. We require a convex mirror sighted on the appropriate telegraph pole or do we have to have an accident to qualify? Surely the cost of such a safety measure is justified. We already have such an arrangement at the Shoulder of Mutton/Smith Gutter Lane junction so there is a precedent already.

Scotch Corner/A1 update makes no provision for extra traffic lights to serve exit from the Service area especially on Friday afternoons and there is no provision for residents to gain access to the roundabout only by taking a risk of joining traffic coming from the North and West which again is dangerous because they alternate without an adequate gap. When I questioned a rep of the RDC he maintained that lights were only to keep main traffic flowing. Since ours is minor we do not apparently qualify therefore we are sometimes static for long periods unless one takes a risk.

On the subject of the overall planning of the A1 update as a layman can I query the need for a dedicated bridge over the A1 at Kneeton corner to serve 1 farm! Was this more economical than extending the road behind the Road Works at the Barton interchange to serve the same purpose or am I missing something?

I apologise if any of these matters have been raised and discussed in the past but if so I would appreciate the official responses. Many thanks

[Redacted signature block]

[Redacted vertical line]