

Inglenook House, Main Road



Section: Either a three-unit house or a two-unit house with a one-cell cottage (The Cottage) attached. Central doorway with symmetrical window layout.

Period: 17th Century

Walls: Uncoursed rubble with large semi-dressed quoins. There is an uncoursed rubble porch. A substantial uncoursed rubble built chimney is situated on the gable end, giving rise to an inglenook inside. The chimney on the other side of the building would, from the stepped stone work showing above the new pantiles, appear to have been another inglenook gable end chimney.

Roof: Pan-tiled with parapet at east gable end.

Windows: The ground floor windows are twelve pane horizontal sliding windows with stone lintel and sill. On the first floor there are two six pane side-sliding windows with a four pane side-sliding located centrally over the door. All have stone lintels and sills. On the gable end is a blocked single-light window with chamfered surround to the first floor and loft.

Door: Wooden door with wooden architrave set in wall stone.

Points of interest: Inglenook chimneys (described above).

